Page 1

May 5, 2010 9:21:51 AM

Item ID:

D412-742-043

**Revision ID:** 

Item Name: **Start Date:** 

5/05/10

Required Date: 5/12/10

Replacement Float Skidtube

Start Qty: 1.00 Req'd Qty: 1.00



Accept

**Cust Item ID:** 

Date:

**Customer:** 

Setup Start

Stop

Reference:

Approvals:

Process Plan:

QC:

Date:

Date:

SPC (Y/N):

**Tooling:** 

Date:

Run

Qty

Start

Stop

Sequence 1D/ Work Center ID Operation Description

**Revision Nbr** 

Set Up/ **Run Hours**  Draw Number Draw Plan Rev.

Accept Qty Code

Reject

Reject Insp. Number

Stamp

Draw Nbr

D3391

Rev H

Document Control

DOCUMENT CONTROL

Memo

0.00

0.00

Photocopy bluefile and create labels per PPP D412-742-043 CHG004 N/A / Pull who 58652

W/O:			IGES							
DATE	STEP	PR	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								. !		
	:									
		·								
Part No	:	PAR #:	Fault Ca	tegory:	NCR	Yes N	lo DQA	۸:	Date:	
Resolution:			Disposit	Disposition: QA: N/C Closed:					Date:	
NCR:			WORK OR	DER NON-CONFORI	MANCE	(NCR)				
DATE STEP		Description of NC			ection B	Verification verification		ation		Approval
	1	Section A	Initial Chief Eng	Action Descriptio	n	Sign & Date	Section	on C	Chief Eng	QC Inspector
						-		,		
NOTE: D	ate & initia	al all entries					<u> </u>		<del></del>	

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

### Work Order ID 58382

May'5, 2010 9:21:51 AM

Required Date: 5/12/10

Item ID:

D412-742-043

Accept



Setup Start

**Revision ID:** 

Item Name:

Replacement Float Skidtube

5/05/10

Start Qty: 1.00

Reg'd Qty: 1.00

**Cust Item ID:** 

**Customer:** 

Reference:

**Start Date:** 

Approvals:

Process Plan:

Date:

**Tooling:** 

Date:

Run Start

QC:

Date:

SPC(Y/N):

Date:

Stop

Stop

Sequence ID/ **Work Center ID** 

110



HandFinish

Hand Finishing

Operation **Description** 

HandFinishing

Set Up/ **Run Hours** 

0.00

0.00

Draw Number

Plan Draw Rev. Code

Reject Accept Qty **Oty** 

Number

Insp. Stamp

10/07/07

1-Install tubes together and seal them all the way around using Sikaflex

∠41/291. Ensure tube ends line-up with saddle holes for proper alignment, using

A/R:111Sikaflex-241/-29111 MU113514 Expiry date: | / (5 / / 1

2-Install wearplates as per Dwg D3391. Ensure that plastic washers are against wearplate, then topped with the SS washer. Seal all bolts with sikaflex exept ones with inserts on inside of tube, hand tighten only bolts with no sikaflex.

A/RIHISikaflex-241/-29111<u>M 113 519</u> Expiry date: H 10 4

3-Remove "T" pins once sikaflex is dry.

4-Coat all exposed hardware with LPS Procyon. Remove any excess off with MEK degreaser.

A/RITHLPS Procyon 1 M 10425/

Dart Aerospace Li
-------------------

W/O:				WORK ORDER CHANGES						
DATE	STEP		PRO	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						1				
Part No	i Nur	2-742-043	PΔR #·	Fault Category: Skick Aube	NCD:	) DQ	<u> </u>	Patas		
		Resolution:	-work	Disposition:		Closed:	leu	Date: _	10/07/08	

NCR: 58382		WORK ORDER NON-CONFORMANCE (NCR)									
DATE STEP		Description of NC		Corrective Action Section B	Verification	Approval Chief Eng	Approval QC Inspector				
		Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date			Section C			
10.07.17	ווט	Fud scoldle have won it all our built to be installed,	10.07.07 91 an	Acceptable to file  Inner hole to allow  built to install so 0.008	20/101	Salata	10,07.07 951 UP	Salaha			
								,			
				,							

### Work Order ID 58382

May 5, 2010 9:21:52 AM



Page 3

Item ID: **Revision ID:** Item Name:

D412-742-043

Replacement Float Skidtube

5/05/10 **Start Date:** Required Date: 5/12/10 Start Qty: 1.00

Req'd Qty: 1.00



Accept



Setup Start



Stop

Reference:

**Approvals:** 

**Process Plan:** 

Date:

Tooling:

0.00

Date:

Run Start

Stop



QC:

Date:

SPC (Y/N):

Date:

Draw

Rev.

Sequence ID/ **Work Center ID** 

120

QC

Quality Control

Operation **Description** 

Packaging

QC5- Inspect part completeness to step on W/O

Set Up/ **Run Hours** 

Draw Number

**Cust Item ID:** 

**Customer:** 

Plan Accept Qty Code

Reject Qty

Reject Number

Insp. Stamp

Memo

30/FUE1 3 000

130



Packaging

Packaging

0.00

0.00

Memo

Identify and pack for shipping as per PPP D412-742-043

PPP Rev:

Location:

10.7.84

140



Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

MF 10-7-8

• Dart	Aero	space	Ltd
--------	------	-------	-----

W/O:			٧	VORK ORDER CHA	NGES					
DATE	STEP					Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·							
							}			
Part No	:	PAR #:	Fault Ca	tegory:	NCF	R: Yes	No DQA:		_ Date: _	
Resolution:			Disposit	Disposition: Q					Date:	
NCR:		·	WORK OR	DER NON-CONFOR	RMANCE	(NCR	)			
DATE	STEP	Description of NC	Corrective Action Section B				Verifica	ition	Approval	Approval
DAIL	O.L.	Section A	Initial Chief Eng	Action Description Chief Eng	on	Sign & Date	Section		Chief Eng	QC Inspector
								:	!	
									į	
				~						
					:		*****			
-										
		•								
							-			
									:	

### **Picklist Print**

May 5, 2010 9:21:49 AM

Work Order ID: 58382

Parent Item Name:

D412-742-043

Replacement Float Skidtube

Comments:

4 12 04 4

Parent Item:

IPP Rev Al 105.10.13 | New Issue

IPP Rev B: 06.02.13; ECN 773 dwg @ rev.D

IPP Rev:C 07-05-28

IPP Rev:D 07-12-04

As per Rev F

ECN 1072

KJ/JLMI I

EC JLM

DD verified by:JLM

**Start Date: 5/05/10** 

Required Date: 5/12/10

Start Qty: 1.00

Required Qty: 1.00

AN3C4A	
BOLT	

Purchased

No

No

No

110

Each

2,029.000

24

		1 18

Location	Loc	<u>Oty</u>	Loc Code				
ST350	:	2029 -13	51672		x24	<b>W</b> E	10107107
114103		501	1111859	,			
114108		$_{300}$ /	()( 11702 (				
114416		228					
114523		1000					
	110	Each	581.0000	12			



**BOLT** 

Location ST351

NAS1149(0332R / K) 115000

Loc Qty

Loc Code

X12 161 10107107



Purchased

Purchased

(11982)

110

Each

581

581

269.0000





Purchased

110

100 Each

0.0000

x44 9/ 10/07/07

48 HI 10107107



washer

**BOLT** 

D3391-021

AN960C10L

Fwd Tube Assembly

Manufactured

110

Each

0.0000

W/O: WORK ORDER CHANGES				GES							
DATE	STEP	PROC	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•									
											Î
				·							
Part No	:	PAR #:	_ Fault Ca	tegory:		NCF	R: Yes I	No DQ	٨:	Date:	
		Disposition:			QA:	QA: N/C Closed:			Date:		
NCR:		W	ORK OR	DER NOI	N-CONFORM	ANCE	(NCR	)			
DATE	STEP	Description of NC	Description of NC Corr			Section B Veri			cation Approval	Approval	Approval
	J.L.	Section A	Initial Chief Eng	Act	ion Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
							·				
	, .								į		
							•				

### **Picklist Print**

May 5, 2010 9:21:49 ÅM

Work Order ID: 58382

D412-742-043

Parent Item Name:

Replacement Float Skidtube

Comments:

Parent Item:

IPP Rev At 105.10.13 | New Issue |

IPP Rev B: 106.02.131 ECN 773 dwg @ rev.D

IPP Rev:C 07-05-28

IPP Rev:D 07-12-04

As per Rev F

ECN 1072

KJ/JUMI ! EC

JLM

DD verified by:JLM

40522

D3391-023

Manufactured

Manufactured

No

No

110

Each

1.0000

**Start Date: 5/05/10** 

Start Qty: 1.00

Mid Tube Assembly

Location

FP

B56441

110

Loc Oty

Loc Code

1.0000

x1 10 107 107

Required Date: 5/12/10

Required Qty: 1.00

Aft Tube Assembly

Location

Location

FP

Loc Qty

Loc Code

下010011尺

D3564-1



Wearshoe

Manufactured No

No

1356219 48122 110

Each

Each

11.0000

Manufactured

FG 33798 FP

**(**51676**)** 

2 110 Each

Loc Qty

Loc Code

11.0000

Il 10/07/07

Loc Qty

2

9

Wearshoe

D3564-3

Location FG

FP19

33764

65489

Loc Code

Folson M1x

W/O:			WC	RK ORDER CHAN	GES			•		
DATE	STEP	PRO	OCEDURE CHA	NGE	В	/	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·						,
Part No	•	PAR #:	Fault Cate	gory:	NCR: \	es N	lo <b>DQ</b>	A:	Date:	
<u>.</u>				Disposition: QA: N/C Closed: Date						
NCR:			WORK ORDI	ER NON-CONFORM	MANCE (N	ICR)				
DATE	STEP	Description of NC	Corrective Action Section				Verific	ation	Approval	Approval
	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		gn & ate	& Section C		Chief Eng	QC Inspector
					-				·	

### **Picklist Print**

May 5, 2010 9:21:50 AM

Work Order ID: 58382

Parent Item:

D412-742-043

Parent Item Name:

Replacement Float Skidtube

Comments:

IPP Rev A 105.10.13 | New Issue |

IPP Rev BI 106.02.131 IECN 773 dwg @ rev.D

IPP Rev:C 07-05-28 IPP Rev:D 07-12-04

As per Rev F

Manufactured

ECN 1072



KJ/JLM11

EC JLM

DD verified by:JLM

**Start Date:** 5/05/10

Required Date: 5/12/10

10/07/02

Start Qty: 1.00

Required Qty: 1.00

D3564-5

Manufactured

No

110

Each

9.0000

Wearshoe

<u>Locatio</u>	<u>ne</u>	Loc	<u>Qty</u>	Loc Code
FG			1 13	58709
	34806		1	,
FP19			8	
	57525		1	
	57729		7	
		110	Fach	45,0000

D3566-1



Gasket

<u>Location</u>	Edt Qty	<u>Lot Cout</u>
FG	1	B58709
34806	1	,
FP19	8	
57525	1	
57729	7	
	110 Ea	45.0000

<b>Location</b>	Loc Qty	Loc Code
FP015	45	B59126
57715	24	
(8182)	21	
1	0 Each	23.0000

Manufactured No

No

D3566-5

Gasket


Location	Loc Qty	Loc Code
FP015	23	
57 <u>5</u> 26	3	
7682	20	

VI 94 (0107/02


x1 x1 1010767

FO/FO/ 10/ 12/1X


	•									
W/O:			WC	ORK ORDER CHANC	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR	: Yes	No <b>DQ</b> /	A:	Date:	
			Disposition: Q							
NCR:				ER NON-CONFORM						
DATE	STEP	Description of NC	Corrective Action Initial Action Descrip		tion B	C: 0	Verific	ation	Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
·										
	.									




	-							•	
W/O:			WC	ORK ORDER CHANGE	S				-
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·					
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	
	R	esolution:	Disposition	Disposition: QA: N/C Closed: Date:					
NCR:		V	VORK ORDI	ER NON-CONFORMA	NCE (NC	R)			
DATE	STEP Description of NC Section A			n B	Verific	cation	Approval	Approval	
			Initial Chief Eng	Action Description  Chief Eng	Sign Date	&   Secti	on C	Chief Eng	QC Inspector
								·	
	·								
							•		
	,								
	1		1		1				




W/O:			V	ORK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Ca	tegory:	NCR: Ye	s No DO	QA:	Date:	
		solution:							
NCR:				DER NON-CONFORM					
DATE	STEP	Description of NC	Corrective Action Initial Action Descript		tion B		fication	Approval	Approval
		Section A	Chief Eng	Chief Eng	Dat		ction C	Chief Eng	QC Inspector
			-						
				·					
				·					



W/O:			WO	RK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•										
Part No	:	PAR #:	Fault Cate	jory:	NCI	R: Yes	No <b>DQ</b>	A:	_ Date:	
				Disposition: QA: N/C Closed: Date:						
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCR	)		· · · · · · · · · · · · · · · · · · ·	
DATE	STEP Description of NC Section A		Corrective Action Section				Verifie	cation	Approval	Approval
DATE			Section A Initial Action Desc Chief Eng Chief Er		otion Sign & Date		ign & Section C		Chief Eng	QC Inspector
<del></del>										*****
								:	:	




W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b> A	\  <b>\</b> :	Date:					
		solution:											
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCR	)							
DATE	STEP	Description of NC	Initial	Corrective Action Section Action Description	on B   Sign &	Verific		Approval	Approval				
		Section A	Chief Eng	Chief Eng	Date	Section	on C	Chief Eng	QC Inspector				
							·						




1.

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
·									
Part No		PAR #:							
			Disposition	on:	_ QA: N/C C	losed:		Date:	
NCR:		1	WORK ORE	ER NON-CONFORMA	NCE (NC	R)			
DATE	STEP Description of NO			Corrective Action Section		Verifi	cation	Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	& Sect	ion C	Chief Eng	QC Inspector
									•




W/O:			W	ORK ORDER CHANGI	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								<b>.</b>	
				`					
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQ</b>	A:	Date: _	
	R	esolution:	Disposition	n:	QA: N/C C	losed:		Date: _	
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NCI	R)			
DATE	STED	Description of NC	Initial	Corrective Action Section		Verific	cation	Approval	Approval
DATE	SIEF	STEP Description of NC Section A		Action Description Chief Eng	Sign Date	な Secti	ion C	Chief Eng	QC Inspector
					:				
			·						
-								,	
					i i			l	



Dart Aerosi	pace Ltd
-------------	----------

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector			
									:			
·												
		PAR #:	Fault Cate	egory:	NCR: Yes	No DQ	A:	Date:				
		solution:										
NCR:			WORK ORD	ER NON-CONFORM	IANCE (NCF	R)						
DATE	STEP	Description of NC	1.20	ction B	Verific	ation	Approval	Approval				
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector			
				•								



Dart	Aer	osp	ace	Ltd
------	-----	-----	-----	-----

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
									1			
								ā		·		
Part No	•	PAR #:	Fault Cate	egory:	NCI	R: Yes	No <b>DQ</b>	\:	Date:			
Resolution:												
NCR:				ER NON-CONFO								
DATE	STEP	Description of NC	Corrective Action Section				Verification		Approval	Approval		
DAIL	SILP	Section A	Initial Chief Eng	Action Descript Chief Eng	tion	Sign & Date	Section		Chief Eng	QC Inspector		
							1					
	1	1					1		I	-		

DRAWING N	0.	TITLE		REV. H	DART A	<b>EROS</b>	PACE USA, II	VC D.E.	O. NO.	SH	EET NO.		SCALE
D3391		,412 FLOAT	SKIDTUBE	1	ENG	NEEF	RING ORDER	D33	91-H-1	SHE	ET 1 OF, 1		NTS
DRAWN	(f	)	CHECKED	<u>l</u>	MFG. AF	PR.	Δ	APPROV	ED NW	DE APP	₹. <b>-</b> #	> ,	
DATE	09.09.	23	DATE	04.04.24	DATE	09/	109125	DATE	09/09/30	DATE	09/00	1/30	

**PURPOSE:** 

LPS-3 IS NO LONGER USED DURING ASSEMBLY OF D3391-041/-043 SKIDTUBES.

CHANGE:

AMEND NOTE 2 OF D3391-041/-043 SKIDTUBE ASSEMBLIES (ZN A6-1, A6-2) AS FOLLOWS:

2) SPRAY INSIDE OF TUBE WITH A COAT OF LPS LABORATORIES "LPS-3" AFTER FINISH-AND AFTER INSTALLATION OF INSERTS. COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS OFF POWDER COATING WITH MEK DEGREASER.

DELEASED 2010 -02- 0 2

No 58282

COPYRIGHT © 2009 BY DART AEROSPACE USA, INC

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DATA REROSPACE USA, INC.

Dart	Aero	space	Ltd
------	------	-------	-----

W/O: WORK ORDER CHANGES												
DATE	STEP	PRO	CEDURE CH	IANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
										· ·		
										•		
Part No:		PAR #:	Fault Ca	tegory:		NCF	R: Yes N	o DQA	\:	Date:		
		esolution:	Disposit	ion:		QA:	QA: N/C Closed: Date:					
NCR:		V	VORK OR	DER NON-	CONFORM	<b>JANCE</b>	(NCR)		-		•	
DATE	STEP	Description of NC	Corrective Action Section B				Verification			Approval	Approval	
		Section A	Initial Chief Eng		Description Chief Eng	1	Sign & Date	Section	n C	Chief Eng	QC Inspector	
							•		9	*•		
					4							
				· · · · · · · · · · · · · · · · · · ·								
								f				
	,											
						,				•		